

Rev 1: September 2018 FSN Ref: 414091 FSCA Ref: 414091

Date: 26:05:2023

## **Urgent Field Safety Notice**

# Intersurgical Superset Fixed Elbow Catheter Mount 22F-22M/15F ≥ 70mm-150mm

For Attention of\*: All clinical staff, Managers and users of the above product.

Contact details of local representative (name, e-mail, telephone, address etc.)\*

Giedrius Budrys Customer Resolution and Relationship Manager Intersurgical UAB Arnioniu str 60, LT-18170 Pabrade Lithuania

Email: giedriusb@intersurgical.lt

Tel. +370 387 66611 Fax: +370 387 66622

or

This could be a distributor or local branch of the manufacturer. To be added at the appropriate stage in the different local languages



Rev 1: September 2018 FSN Ref: 414091

FSCA Ref: 414091

## **Urgent Field Safety Notice (FSN)**

# Intersurgical Superset Fixed Elbow Catheter Mount 22F-22M/15F ≥ 70mm-150mm

#### Risk addressed by FSN

1. Information on Affected Devices*						
1.	1. Device Type(s)*					
	Catheter Mount					
1.	Commercial name(s)					
	Superset Fixed Elbow Catheter Mount 22F-22M/15F ≥ 70mm-150mm					
1.	Unique Device Identifier(s) (UDI-DI)					
	N/A					
1.	Primary clinical purpose of device(s)*					
	To make secure gas tight connections to other respiratory standard taper connectors and / or provide a respiratory pathway between a breathing system and a patient's airway, facemask, suction ports or monitoring ports.					
1.	5. Device Model/Catalogue/part number(s)*					
	REF: 3502000					
1.	6. Software version					
	N/A					
1.	7. Affected serial or lot number range					
	Lot: 7220483					
1.	Associated devices					
	N/A.					

2. Reason for Field Safety Corrective Action (FSCA)*					
2.	Description of the product problem*				
	We have received reports of the patient elbow disconnecting from the Superset tube in a				
	number of products.				
2.	2. Hazard giving rise to the FSCA*				
	Whilst the security of connections should be checked during pre-use checks as per the				
	Instructions For Use provided, if disconnection of the patient elbow was to occur in use, ventilation of the patient could be compromised.				
	ventilation of the patient could be compromised.				
2.	3. Probability of problem arising				
	1:10,000 - 1:1,000				



Rev 1: September 2018 FSN Ref: 414091

4091 FSCA Ref: 414091

2.	4. Predicted risk to patient/users						
	Major risk of harm and possible occurrence.						
2.	5. Further information to help characterise the problem						
	N/A						
2.	6. Background on Issue						
	Intersurgical has received reports, where the patient elbow has disconnected from the Superset tube due to an insecure connection. This is a result of a process non-conformity						
	during the assembly of the catheter mount, where the patient elbow is not fully inserted in						
	to the Superset tube beyond the clip feature that secures it in place.						
2.	7. Other information relevant to FSCA						
	The manufacturing process for the Catheter Mount has been investigated and the problem						
	resolved. No other Lot numbers or products are affected.						
İ							
	O Toma of Antion to militario (L. 1914)						
3.	<ul><li>3. Type of Action to mitigate the risk*</li><li>1. Action To Be Taken by the User*</li></ul>						
ა.	1. Action to be taken by the oser						
	oximes Identify Device $oximes$ Quarantine Device $oximes$ Return Device $oximes$ Destroy Device						
	☐ On-site device modification/inspection						
	☐ Follow patient management recommendations						
	☐ Take note of amendment/reinforcement of Instructions For Use (IFU)						
	□ Other □ None						
	Identify and immediately quarantine any remaining stock of the affected code and lot number listed above and do not use these devices. Please complete the Reply Form to confirm the products have been disposed of locally or to arrange collection of the devices and a credit. If you have no affected devices in stock, please confirm this using the Reply Form. Return the completed Reply Form to to giedriusb@intersurgical.lt (local contact e-mail address).						
	Please continue to report to Intersurgical any adverse events involving this product.						
3.	2. By when should the Immediately on receipt of this FSN and ongoing until no						
	action be completed? affected stock listed in this FSN is remaining.						
3.	3. Particular considerations for:						
	Is follow-up of patients or review of patients' previous results recommended?						
	Not applicable.						
3.	4. Is customer Reply Required? * Yes  (If yes, form attached specifying deadline for return)						



Rev 1: September 2018

FSN Ref: 414091 FSCA Ref: 414091

3.	5.	5. Action Being Taken by the Manufacturer					
			device modification/insp	action			
			abelling change	Solion			
		☐ Other ☐ None	aboning onango				
		B 1 1111	0 1 1 1 1 1	FON			
3	6.		e month of receipt of th	e FSN			
	7	action be completed?					
3.	/.		to be communicated to the patient No				
3	Я	/lay user?  8. If yes, has manufacturer provided additional information suitable for the patient/lay					
	0.	user in a patient/lay or non-profess					
		No					
		4. G	eneral Information*				
4.	1.	FSN Type*	New - Recall				
4.	2.	For updated FSN, reference	N/A				
_	_	number and date of previous FSN					
4.	3.	For Updated FSN, key new informa	ition as follows:				
		N/A					
4.	4.	Further advice or information	No				
		already expected in follow-up					
		FSN? *					
	5. If follow-up FSN expected, what is the further advice expected to relate to:						
4	N/A						
	6.	Anticipated timescale for follow-up	N/A				
4		FSN					
4.	7.	Manufacturer information					
	(Fc	(For contact details of local representative refer to page 1 of this FSN)					
		a. Company Name	Intersurgical Ltd.				
		b. Address	Crane House, Molly	Millars Lane, Wokingham			
			Berkshire, RG41 2R	•			
		c. Website address	https://www.intersu	rgical.com			
4.	8. The Competent (Regulatory) Authority of your country has been informed about thi			as been informed about this			
		communication to customers. *					
4.	9.	List of attachments/appendices:	Customer Reply Form				
4.	10. Name/Signature		Ivan Seniut, Group Quality and Regulatory				
			Affairs Director, Inte	ersurgical			



Rev 1: September 2018 FSN Ref: 414091

ef: 414091 FSCA Ref: 414091

#### **Transmission of this Field Safety Notice**

This notice needs to be passed on all those who need to be aware within your organisation or to any organisation where the potentially affected devices have been transferred. (As appropriate)

Please transfer this notice to other organisations on which this action has an impact. (As appropriate)

Please maintain awareness on this notice and resulting action for an appropriate period to ensure effectiveness of the corrective action.

Please report all device-related incidents to the manufacturer, distributor or local representative, and the national Competent Authority if appropriate, as this provides important feedback..\*

Note: Fields indicated by \* are considered necessary for all FSNs. Others are optional.